

3701:1-48-24 Notifications.

- (A) In addition to the reporting requirements specified in rules 3701:1-40-20 and 3701:1-38-23 of the Administrative Code, each licensee shall provide a written report to the director, within thirty days of the occurrence of any of the following incidents involving radiographic equipment:
 - (1) Unintentional disconnection of the source assembly from the control cable;
 - (2) Inability to retract the source assembly to its fully shielded position and secure it in this position; or
 - (3) Failure of any component (critical to safe operation of the device) to properly perform its intended function.

- (B) The licensee shall include the following information in each report submitted under paragraph (A) of this rule, and in each report of overexposure submitted under paragraph (C) of rule 3701:1-38-21 of the Administrative Code which involves failure of safety components of radiography equipment:
 - (1) A description of the equipment problem;
 - (2) Cause of each incident, if known;
 - (3) Name of the manufacturer and model number of equipment involved in the incident;
 - (4) Place, date, and time of the incident;
 - (5) Actions taken to establish normal operations;
 - (6) Corrective actions taken or planned to prevent recurrence; and
 - (7) Qualifications of personnel involved in the incident.

- (C) Any licensee conducting radiographic operations or storing radioactive material at any location or temporary job site not listed on the license for a period in excess of one hundred eighty days in a calendar year, shall notify the director prior to exceeding the one hundred eighty days.

Five Year Review (FYR) Dates: 04/04/2016 and 04/01/2021

CERTIFIED ELECTRONICALLY

Certification

04/04/2016

Date

Promulgated Under:	119.03
Statutory Authority:	3748.04
Rule Amplifies:	3748.06, 3748.07
Prior Effective Dates:	10/20/2002, 3/22/07, 1/1/12