

3701:1-58-103

Report of a leaking source.

A licensee shall file a report within five days if a leak test required by rule 3701:1-58-27 of the Administrative Code reveals the presence of one hundred eighty-five becquerels (0.005 microcurie) or more of removable contamination. The report must be filed with the address listed in rule 3701:1-40-04 of the Administrative Code. The written report must include the model number and serial number if assigned, of the leaking source; the radionuclide and its estimated activity; the results of the test; the date of the test; and the action taken.

Five Year Review (FYR) Dates: 06/12/2015 and 06/01/2020

CERTIFIED ELECTRONICALLY

Certification

06/12/2015

Date

Promulgated Under: 119.03
Statutory Authority: 3748.02, 3748.04
Rule Amplifies: 3748.04
Prior Effective Dates: 8/15/2005, 10/4/10