

**Labeling, storage, and transportation.**

- (A) The licensee may not use a source changer or a container to store licensed material unless the source changer or the storage container has securely attached to it a durable, legible, and clearly visible label bearing the standard trefoil radiation caution symbol conventional colors, i.e., magenta, purple or black on a yellow background, having a minimum diameter of twenty-five millimeters, and the wording "CAUTION\* RADIOACTIVE MATERIAL NOTIFY CIVIL AUTHORITIES (or "NAME OF COMPANY") \* \_\_\_\_\_ or "DANGER"."
- (B) The licensee may not transport licensed material unless the material is packaged, and the package is labeled, marked, and accompanied with appropriate shipping papers in accordance with Chapter 3701:1-50 of the Administrative Code.
- (C) Locked radiographic exposure devices and storage containers must be physically secured to prevent tampering or removal by unauthorized personnel. The licensee shall store licensed material in a manner which will minimize danger from explosion or fire.
- (D) The licensee shall lock and physically secure the transport package containing licensed material in the transporting vehicle to prevent accidental loss, tampering, or unauthorized removal of the licensed material from the vehicle.

Five Year Review (FYR) Dates: 04/04/2016 and 04/01/2021

CERTIFIED ELECTRONICALLY

\_\_\_\_\_  
Certification

04/04/2016

\_\_\_\_\_  
Date

Promulgated Under:	119.03
Statutory Authority:	3748.04
Rule Amplifies:	3748.06, 3748.07
Prior Effective Dates:	10/20/2002, 3/22/07